JABIRU AIRCRAFT PTY LTD

P.O. Box 5792 Bundaberg West Queensland, Australia. Phone: Fax: Email: +61 7 4155 1778 +61 7 4155 2669 info@jabiru.net.au

SERVICE BULLETIN: JSB 022-2

Issue: 2

Date: 20th June 2014

Subject: Propeller Flange Attachment

| 1 | APPLICABILITY | 1 |
|---|---------------|---|
| 2 | BACKGROUND | |
| | PROCEDURE | |
| J | | |

1 Applicability

All Jabiru Engines.

Note: For aircraft in Light Sport Aircraft categories this Bulletin is equivalent to a Manufacturer's Safety Directions.

2 Background

Recently there has been an concerns raised regarding the inconsistencies between the previous issue of this service bulletin (i.e. JSB 022-1) and the Engine Overhaul Manual (JEM0001-5) regarding the instructions for installation of the Propeller Flange onto the Engine Crankshaft.

This Bulletin is intended to direct the operator to the correct procedure.

3 Procedure

The current version of the Engine Overhaul Manual JEM0001 (revision -5 at the time of writing) contains the **correct** procedure for the installation of the propeller flange onto the engine crankshaft. This procedure must be strictly adhered to.

Furthermore the information provided in the previous version of this service bulletin (JSB 022-1) must be **discarded** as this service bulletin is no longer active or applicable.